

Recall*Chek*[®]

Report Prepared Exclusively for:

John Smith

For the Property Located at:

**12331 Main St
Carmel, IN 46033**

On:

10/20/2014



Report Provided By:



**Test Company Inspections
(317) 999-9999**

See Next Page for Report Summary

RecallChek[®]

Introduction

Important

This report is intended for the use of the listed client and only for the address listed, for the appliances reported on the date indicated. The format of this report, and its content, is the property of RWS, and shall not be duplicated or distributed without the express written consent of RWS. Acceptance of this report indicates the acceptance of these terms.

Terms and Conditions:

Residential Warranty Services Inspector Services Group (RWS) will research and report to the end client directly, any and all potential manufacturer recall issues that have been reported to the U.S. Federal Government including to the CPSC, as well as the Canadian Federal Government including Health Canada, inclusive of all reports as of the day of the inspection back to January 1st, 1974. RWS is not responsible for inaccurately reported data, either from the field inspector or from the manufacturer, and furthermore shall only be held liable for any claims made by any party up to the cost of the report. This limit of liability shall extend to the field inspector as well. All reports will be submitted to the client within two business days of receipt of the appliance list.



These terms were agreed to at time of inspection.

Brought to You By:



Test Company Inspections

(317) 999-9999

www.YourWebsiteHere.com

RecallChek[®]

General Safety Notices

*Based on the age of your home and the utilities delivered to it.

1. Window Blinds/Curtains with "loop" style Cords.

Window blinds with pull cords and inner cords forming a loop can become wrapped around a persons neck and cause serious harm. About 85 million units sold each year. Over 160 incidents reported since 1991.

Remedy: Call Window Covering Safety Council for free repair kit: 800-506-4636 or visit www.windowcoverings.org.

2. Consider Installing Carbon Monoxide Detectors if your Home uses Natural Gas.

Natural gas in homes has an incredible safety record. It is lighter than air, meaning that leaks and accidental discharges of gas dissipate very quickly and are rarely combustible. Most all gas appliances have multiple safety switches to prevent fires and carbon monoxide poisoning. That being said, there is a risk of Carbon Monoxide poisoning whenever combustible gases are involved.

3. Water Heater Safety Issues in Units Manufactured prior to July 1st, 2003.

Units manufactured on or after July 1st, 2003, are highly recommended as a replacement for any gas water heaters manufactured prior to that date that are still in operation. These units cause around 800 residential fires resulting in an average of 5 deaths and 130 injuries annually. Newer units prevent flammable vapor ignition in the area of the water heater thru the implementation of what is referred to as a "flame arrestor", whereby flashback fires are prevented by burning the gas vapors inside of the heater while greatly reducing the risk of igniting flammable gases nearby.

Notes/Exceptions:

Please note- Model numbers were provided for most of your appliances. Other than those exclusions noted, RWS guarantees it will find any recalls reported by the manufacturer to the federal government on or prior to the date the check was ordered. If we fail to find a recalled item for which we were given the correct model number, we will refund any fees charged for this report and pay you \$50 as a reward for finding the deficiency. (Limit one per household).

Please note- this report only covers items which can be classified as real property (**only appliances that are attached to the home are classified as real property**).





Please note- any duplicate items will only be reported once.


RecallChek[®]

Summary of Findings

Total Potential Recalls:

1

Appliance Info	Recalls	Status
Appliance: Dishwasher Brand: Maytag Model: DU954641234 Serial: NW394564156	Very Likely Recalled Appliance	 *95% Match
<p>*Recommendation: The data provided strongly indicates that there is a recall on this appliance. It is recommended that a phone call to the manufacturer be made to determine whether there is a recall on this appliance outstanding. The phone number for the manufacturer can be found in the next section of this report.</p>		
Appliance: Microwave Brand: GE Model: KL00464755 Serial: XC789789	No Recalls	 *0% Match
Appliance: Air Conditioner Brand: Bryant Model: ML456123123456 Serial: LT56456123123	No Recalls	 *0% Match
Appliance: Furnace Brand: Bryant Model: JGT546151 Serial: MBW564561WW	No Recalls	 *0% Match

<p>Appliance: Water Heater Brand: A.O. Smith Model: ADM4561231 Serial: KR456456456TT</p>	<p>No Recalls</p>	 <p>*0% Match</p>
--	-------------------	--



RecallChek[®]

Potential Recall Issue

The following pages of this report contain the details for each potential recall noted in the summary. These details include the requirements for each recall, and who to contact to remedy the problem. The information found here is not necessarily specific to any of the appliances found on the property.

Release Number	10 - 255
Original Date	6/3/2010
Revised Date	

The Original and Revised Date above are when the recall report was released by the manufacturer. When referring to this recall with a manufacturer or with the CPSC, use whichever date is later.

Manufacturer	Maytag
Brand	Maytag, Amana, Jenn-Air, Admiral, Magic Chef, Performa, Crosley
Name of Product	Dishwasher
Units Sold	N/A
Made In	USA

The manufacturer and brand name listed above are the most common names for this product. When verifying if your appliance is part of a Recall, it is best to rely on the Model numbers first, then Serial Numbers or Date Codes/Manufacturing Numbers.

RecallChek[®]

Contact Numbers Regarding This Recall Report

Contact Type 1 Contact Number 1	Firm's Recall Hotline (800) 544-5513
Contact Type 2 Contact Number 2	CPSC Recall Hotline (800) 638-2772
Contact Type 3 Contact Number 3	CPSC Media Contact (301) 504-7601

Potential Hazard Posed by the Appliance:

An electrical failure in the dishwasher's heating element can pose a serious fire hazard.

Incidents Reported, if any:

Maytag has received 12 reports of dishwasher heating element failures that resulted in fires and dishwasher damage, including one report of extensive kitchen damage from a fire. No injuries have been reported.

This Product was Sold thru the following:

Department and appliance stores and by homebuilders nationwide from February 2006 through April 2010 for between \$250 and \$900.

Recall Description as Reported by the Manufacturer:

The recall includes Maytag, Amana, Jenn-Air, Admiral, Magic Chef, Performa by Maytag and Crosley brand dishwashers with plastic tubs and certain serial numbers. Units with Stainless Steel tubs are not included in this recall. The affected dishwashers were manufactured with black, bisque, white, silver and stainless steel front panels. The brand name is printed on the front of the dishwasher. The model and serial numbers are printed on a label located inside the plastic tub on a tag near the left side of the door opening. Serial numbers will start or end with one of the following sequences.

Serial Numbers STARTING With:

NW39, NW40, NW41, NW42, NW43, NW44, NW45, NW46, NW47, NW48, NW49, NW50, NW51, NW52, NY01, NY02, NY03, NY04, NY05, NY06, NY07, NY08, NY09, NY10, NY11, NY12, NY13, NY14, NY15, NY16, NY17, NY18, NY19

OR

Serial Numbers ENDING With:

JC, JE, JG, JJ, JL, JN, JP, JR, JT, JV, JX, LA, LC, LE, LG, LJ, LL, LN, LP, LR, LT, LV, LX, NA, NC, NE, NG, NJ, NL, NN, NP, NR

Resolution for the Potential Recall:

Consumers should immediately stop using the recalled dishwashers, disconnect the electric supply by shutting off the fuse or circuit breaker controlling it, inform all users of the dishwasher about the risk of fire and contact Maytag to verify if their dishwasher is included in the recall. If the dishwasher is included in the recall, consumers can either schedule a free in-home repair or receive a rebate following the purchase of certain new Maytag brand stainless-steel tub dishwashers. The rebate is \$150 if the consumer purchases new dishwasher models MDB7759, MDB7609 or MDBH979; or \$250 if the consumer purchases new dishwasher models MDB8959, MDB8859, MDB7809 or MDB7709. Consumers should not return the recalled dishwashers to the retailer where purchased as retailers are not prepared to take the units back.

Instructions to Contact the Manufacturer in Regards to this Appliance:

For additional information, contact Maytag at (800) 544-5513 anytime, or visit the firm's website at www.repair.maytag.com